a a	Approved For Release 2002/07/24 : CIA-R	DP80-00810A004	1200440009-8	
À	CLASSIFICATION CONFIDENTIAL /20	MTROL H.S. C	PERCHALS ONLY	25X1A
COUNTE	77	REPORT NO		
TOPIC	Motor Vehicle Repair Shop No. I in Budgo	est	William Control of Con	
The state of the second second			635605	· Alla arm. and committee of the arms and a second
EVALUAT	TION 25X1X PLACE OBTAINED			25X1A
<u> </u>	JOE OF THE Day	25X1A	METALON VI. N. M. 1775 AND COLUMN (SALE)	
		- Parameter Annaber (Carlos Company) (Proposition of the Carlos Company) (Proposition of the Carlos Company)	n Samuelphillin Milatiston vähänä pallinka pikuu liinessa. Vääpin senna	1 Providental Conference Conferen
in the table of the f		RED.	30 April 1954	Marie Marie de l'Alexandre de
	NCES			
AGES	ENCLOSURES (NO. & TYPE) 1 BKG	tch on ditto.	with legend	-
EMARK	S			
	TO, LT, SHE TO COME LINE . MANAGE LANGE CO. COME OF CO.	,		Steel etti sähtämissa laikuvassa singis vasassianajasi laiva
MIN SERVICE AND ADDRESS OF THE				
	a termination is a sea resident AUS. Concern viscologists embourance has recommended about the recommendation of the second contract of t	3 MAGE OF A SERVICE STANDARD CONTRACTOR OF THE PARTY OF T		25X1X
1.	The state-cwned Motor Vehicle Repair Shop No covered on area of about 150 x 250 meters an glass roof. Before the plant was nationalize Ford Company. No constructional changes were	C Mas Donsed 1	n a modern buildir	ispest XIII ng with nd by the
2.	The production shops included the engine worthe laths shop, the test driving department; the repair and testing of engines for T-34 to	kshops, the fi	e vero	
3.	In addition to the daily quota of repair workfrom old and salvaged 1.5-ton Dodge trucks. as of 1 July 1950 had the effect that 20 per defective. The entire output was turned over Matyasfould (Q 48/H 62) after each car had be the department for tank engines had a monthly	cent of the vel to the Hungar	the output to eig hicles produced we ian Army Depot in	ht trucks re
40	The repair plant had a work force of about 1, done in one shift. Every six months, new work personnel in addition to the fire department shelters had been repaired.	,000 persons, in	nclading 60 women.	Work was no guard -raid
(1A 1 。	Comenta For a sketch of the plant lay	7out, see Anne:	C u	

Front Layout of Motor Vehicle Repairshop to. I in Budapest

Legend see next page .6 10 12 13 17 KID PKD. 1: 16 19 25. Approved For Release 2002/07/24 : CIA-RDP80-00810A004200440009-8

CONFIDENTIAL ONTROL - U.S. OFFICIALS ONLY

Complemential/Control = U.S. OFFICIALS ON	CO	NETPENEL	AI CONTROL	J.S.	OFFICIALS	OLL
---	----	----------	------------	------	-----------	-----

.. 2 ...

25	X	1	Α

Legenda

- 1 Open area, parking lot for 40 to 60 x 1.5-ton Dodge tracks to be salvaged.
- 2, Farking lot for road-tested 1.5-ton Dodge trucks.
- 3 latekeeper for office personnel.
- Two-story building with so-called culture hall, kitchen, messhall, baths, and offices.
- 5 Unloading place for motor vehicles.
- 6 Assembly hall.
- 7 Disassembly shop for motor vehicles.
- 3 Fitting shop and carpentry.
- 9 Material store of fitting shop.
- 10 Carpentry.
- 11 Fitting shop with two sheet-metal pressing and three sheet-metal cutting machines.
- 12 Paint shop.
- 13 Gate for vehicles and workers.
- 15 Gatekeeper.
- 16 Offices,
- 17 Storage of engine parts and rubber-
- 18 Hallway leading to dressing rooms and baths in the basement.
- 19 Lathe shop:
- 20 Engine-testing department.
- 21 Dismantling and assembly shop.
- 22 Electric workshop.
- 23 Car washing shope
- 24 Repair and testing shop for engines of T-34 tanks.
- 25 Gate for vehicles.
- 25 Gatekeeper-
- 27 Single-story building, 30 x 80 mg housing storages and kindergetten.

CONFIDENTIAL/CONTROL - U.S. OFFICIALS ONLY